

Widerstand eines Pt100- Thermometers in Abhängigkeit von der Temperatur

A 3,91E-03 B 5,78E-07

T in °C	T in K	R(Pt100)
-200	73,15	24,16
-190	83,15	27,84
-180	93,15	31,53
-170	103,15	35,24
-160	113,15	38,96
-150	123,15	42,68
-140	133,15	46,42
-130	143,15	50,18
-120	153,15	53,94
-110	163,15	57,71
-100	173,15	61,50
-90	183,15	65,30
-80	193,15	69,11
-70	203,15	72,93
-60	213,15	76,76
-50	223,15	80,61
-40	233,15	84,46
-30	243,15	88,33
-20	253,15	92,21
-10	263,15	96,10
0	273,15	100,00
10	283,15	103,91
20	293,15	107,84
30	303,15	111,78
40	313,15	115,72
50	323,15	119,68
60	333,15	123,66
70	343,15	127,64
80	353,15	131,63
90	363,15	135,64

